

WindPRO 2.7 Service Pack 3 (Build 473)

We hope you are enjoying working with WindPRO version 2.7. However, a few issues have been discovered after the release, which can be fixed by installing the new Service Pack 3, now available for download.

The issues fixed include:

- An updated WAsP 10 dll. The old one was missing a check for the maximum number of points in a map file.
- A new coordinate system: Bulgarian BGS 2000 Lambert
- A fix for a problem when saving the setup of a calculation that have not yet been calculated.
- A problem with aviation lights in animations has been fixed.
- A fix for a problem in Loss and Uncertainty where the main report map could overlap results.
- A problem where descriptions on WTGs would disappear in reports after the project is saved have been fixed
- A memory leak regarding roughness areas in a Park calculation have been fixed
- A possible error in meteo-analyzer substitution when using missing wind-direction data have been fixed
- An error in Loss calculation with powercurves with no zero-power value have been fixed
- An error in the graphics section of the meteo-analyzer using concurrent turbulence data has been fixed
- Updated Spanish / French / Chinese / German / Romanian translations
- Updated Documentation regarding the installation and activation.